

Massachusetts Pepartment of Environmental Protection Bureau of Waste Site Cleanup



SEMS DocID

621119

EPA ARCS REPORT REVIEW MEMO

Date: April 30, 1996

TO:	Helen	Waldorf

Review of Report:

Vitale Flyash Pit" Final SI/SIP Report

THRU: Harish Panchal

Stone and Webster

FROM: Scott Greene

Δ.	Site	Informa	ation:

Database/ Site ID Number Name of Site

Street Address/ City or Town

EPA CERCLIS #: MAD 981068273

EPA Site Name:

L.P. Henderson Road

Vitale Flyash Pit

Beverly

MA DEP #: RTN 3-0235

DEP Site Name:

L.P. Henderson Road

Vitale Site

Beverly

1. Federal Site Removal Assessment Program Status: (C=completed, IP=in progress, N=Needed)

Comments:

Status	Date Completed	EPA Prioritization
Completed	December, 1987	Low
Completed	April, 1990	Low
Completed	April, 1996	
	Completed Completed	Completed December, 1987 Completed April, 1990

- 2. Status in MA Program: (check one)
- [] Not in MA Database:
- [X] Transition:

[] LTBI [X] Unclassified [] Non-Priority without Waiver

LSP Evaluation Due Date: 8/2/95

LSP Evaluation Submitted Date: Not Submitted

RAO Date Submitted:

NFA Affirmation Date:

[] Non-Priority with Waiver

Date Waiver Expires:

- [] Priority Site with Transition Statement or Major Modification:
 - [] Tier 1A

[X] Tier 1B [] Tier 1C [] Tier II

Site Manager:

* Categorical Tier IB due to failure to submit LSP Evaluation Opinion by 8/2/95

01/26/96

Massachusetts Department of Environmental Protection Bureau of Waste Site Cleanup			
EPA ARCS REPORT	REVIEW MEMO		Page 2
2. Status in MA Program	(cont.):		
[] Release Under the 19	93 et. al. MCP:		
[] RAO Submitted	i: [] < 1 Year (since listing)	[] > 1 Year and No	o Submittal (Tier 1B)
[] Tier Classified:	[] Tier 1A Site Manager:	[] Tier 1B []	Tier 1C [] Tier II
[] Risk Reduction	: []IRA []RAM []URAM	[]CRA	
[] Audit:	[] Follow-up Plan Required	[] Publicly Funded Phase	:
[] Adequately Regulated	(check one): [] CERCLA [] [RCRA [] HSWA [] Solik	d Waste
Summary of Compliance:	Deadlines: [] In Compliance	[X] Out of Compliance	
	Technical: [] In Compliance	[] Out of Compliance [] Not Known
B. Identification of Risk I	Reduction Opportunities:		
1. Imminent Hazard (chec	k one):		
Criteria Met: [] Yes [] N	lo [X] Unknown		
"Imminent H Imminent H	vels of arsenic detected in test pit of Hazard trigger (40 mg/kg). Must delazard Evaluation. Also, arsenic denomination monitoring wells located within the	determine surficial levels to detected in groundwater at levels.	determine need to perform vels exceeding drinking water
a. Steps Taken or to be 1	Taken:		
Notice of Responsibility: State Response Action: Request For Information: Refer to EPA ESD:	[] Sent [] Will Send [] Performed [] Will Perform [] Sent [] Will Send [] Referred [] Will Refer		
Other: Field work s levels of ars	scheduled for spring/summer. Nee senic may indicate need to perform	d to ensure work includes s IRA, including Imminent Ha	surficial soil samples. Elevated azard Evaluation.
b. Results of Checked Ite	ems:		
c. Next Steps of Checked	i items:		
2. Condition(s) Warrantin	ng an immediate Response Actio	n (other than imminent ha	zard) (check all that apply):
[] Sudden Release [] Threat of Sudden Releas [] Oil Sheen on Surface Ware [] Release Detected in Priv [] Release to Storm Drain	later [] Threat of UST Release to Groundw		nce

01/26/96

Massachusetts Department of Environmental Protection Bureau of Waste Site Cleanup EPA ARCS REPORT REVIEW MEMO Page 3 3. Immediate Response Action Status: a. Status: (C=Completed, IP=In Progress, N=Needed) [] Deployment of Absorbent/Containment Materials [] Temporary Covers or Caps [] Soil Vapor Extraction [] Bioremediation [] Product or NAPL Recovery [] Structure Venting System [] Groundwater Treatment System [] Air Sparging [] Temporary Evacuation/Relocation of Residents [] Temporary Water Supplies [] Removal of Contaminated Soils [X] Fencing/Sign Posting/Other Security Measures [] Removal of Contaminated Materials [] Removal of Drums/Tanks/Containers [] Removal of Product From Drums/Tanks/Containers [] Other Response Actions Describe: b. Results of Checked Items: May be required depending upon results of field work. c. Next Steps of Checked Items: C. Outcome Status Summary: [] Referral to Other Agency or Bureau: [] Immediate Response Action Not Triggered [] Immediate Response Action Complete [] Response Action Outcome Complete Other Comments: D. Identification of Environmental Compliance Issues as a Result of Reviewing Report: Long history of compliance issues at this site under former owners (Vitale Brothers). Current owners (City of Beverly) have missed LSP Evaluation Deadline (8/95), but appear willing to perform some site investigation work (scheduled for this spring/summer). May be necessary to send Notice of Non-compliance letter to City to enforce existing (1986) Administrative Order (prevent erosion of fly ash into stream/lake, dredge fly ash from stream/lake). E. DEP Comment on Overall Accuracy of Report:

A ARCS REPORT REVIEW MEMO	Page 4
DEP Recommendation on Further Federal and State A	ction (check one):
Federal (check all that apply)	State (check all that apply)
Preliminary Assessment [] Site Inspection	[X] Immediate Response Action [X] By PRP [] By State
Site Inspection Prioritization	[] Audit
Expanded Site Inspection Expanded Site Inspection and Remedial Investigation Hazard Ranking System Proposed to NPL Final NPL Deleted from NPL Removed from NPL	[] Inspection [] Record Review [] Sampling, Analysis, & Evaluation [] Compliance Assistance [] Enforcement [X] Notice of Non-Compliance [] Penalty Assessment Notice [] Administrative Consent Order [] Unilateral Administrative Order [] Adjudicatory Hearing Appeals [] Referral to:
Other:	[] Attorney General: [] Another Bureau: [] Another Agency: [] Other:
Other Comments:	

01/26/96